

TWISS ANALYTICAL LABORATORIES, INC.

26276 Twelve Trees Lane, Suite C Poulsbo, WA 98370 Telephone (360) 779-5141 FAX (360) 779-5150

IOC - LCR

IOC - LCR by EPA Methods 200.9, 200.7

Distribution System - Report of Analysis

108

IOC - LCR	Group: A
System ID No: IH3826	System Name: Seven Cedars Casino
DOH Source No: S93	County: Clallam
Sample Purpose: RC	Date Received: 12/18/2013
	Date Analyzed: 12/20/2013
	Date Reported: 12/20/2013
Send Report To: Jeff Becker Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382	Bill To: Jeff Becker Jamestown S'Klallam Tribe 1033 Old Blyn Hwy Sequim, WA 98382

DOH #	Lead, mg/L	Copper, mg/L
SRL, mg/L	0.001	0.02
Trigger Level, mg/L	--	--
MCL, mg/L	*	*
Analytical Method (Analyst Init.)	EPA 200.9 KW	EPA 200.7 KW

Sample #	Date Collected	Sample Location	Lead, mg/L	Copper, mg/L
01065901	12/18/2013	CA-03 Kitchen Sink ✓	0.002	0.19
01065902	12/18/2013	CA-04 Deli Sink ✓	0.001	0.07
01065903	12/18/2013	CA-05 Main Bar Sink ✓	0.002	0.74
01065904	12/18/2013	CA-13 Rainshadow Bar sink ✓	0.012	0.95
01065905	12/18/2013	CA-14 Back Bar	0.003	2.37

* Lead has not been assigned an MCL, it has an 'Action Level' of 0.015 mg/L designated by EPA. Copper has not been assigned an MCL, it has an 'Action Level' of 1.3 mg/L designated by EPA.

SRL: (State Reporting Level), indicates the minimum reporting level required by the Washington Department of Health (DOH).

Trigger Level: DOH Drinking Water response level. Systems with compounds detected at concentrations in excess of this level are required to take additional samples. Contact your regional DOH office for further information.

MCL: (Maximum Contaminant Level), If the contaminant amount exceeds the MCL, immediately contact your regional DOH office for further information.

NA: (Not Analyzed), in the results column indicates this compound was not included in the current analysis.

ND: (Not Detected), in the results column indicates this compound was analyzed and not detected at a level greater than the concentration indicated.

< (0.00x): indicates the compound was not detected in the sample at or above the concentration indicated.

Cu action level exceeded 1.66

